Tirunelveli district.

Name of taluk.	Number of ryots.
Nanguneri	376
Tirunelveli	852
Srivaikuntam	779
Sankarankoil	1,872
Tenkasi	388
Tiruchendur	716
Koilpatti	23
Shenkottah	45
Ambasamudram	1,740
Total ..	6,791

APPENDIX XV.

[Vide answer to Unstarred Question No. 416, asked by Sri S. M. Annamalai at the meeting of the Legislative Assembly held on 28th September 1961 page 239 supra].

Statement showing the details of tanks proposed to be repaired under Special Minor Irrigation Programme during 1961 in North Arcot disirict and their estimated cost.

Serial number and name of work. (1)	*Taluk.* (2)	*Estimated cost.* (3)
Under the Control of Chief Engineer (Irrigation)—		RS.
1 Raising the F.T.L. of Vakkadai Mukkur Hissa tank.	Cheyyar.	86,785
2 Restoration of Kattuputhur abandoned tank ..	Tiruvannamalai.	32,000
3 Special repairs to Northampoondi tank	Do.	13,800
4 Special repairs to Poigainallore tank-supply channel.	Arkonam.	8,500
5 Silt clearance to Chengam tank supply channel.	Chengam.	12,500
6 Special repairs to Arasur large and small tank.	Cheyyar.	6,500
7 Special repairs to Pakkam tank supply channel.	Gudiyatham.	6,000
8 Silt clearance to Kalinjur tank supply channel.	Do.	9,500
9 Restoration of blocked Sluice No. 1 of Kavanur tank.	Do.	740
10 Raising the F.T.L. of Vedal tank	Wandiwash.	11,000
11 Silt clearance of Kilvanakkambody tank supply channel.	Chengam.	3,100
12 Silt clearance to Flathur tank supply channel ..	Polur.	4,100
13 Raising the F.T.L. of Meleri tank by 1′-0″ ..	Arkonam.	9,100
14 Silt clearance to Pudupattu tank supply channel.	Do.	9,600
15 Strengthening the banks of Velithangipuram tank supply channel.	Do.	5,500

28th September 1961]

Serial number and name of work.	Taluk.	Estimated cost.
(1)	(2)	(3)
		RS.
Under the Control of Chief Engineer (Irrigation)—cont.		
16 Clearing silt in Kattupakkam Palleri supply channel.	Arkonam	3,000
17 Special repairs to Irumbur large and small tank	Wandiwash.	13,500
18 Shifting off-take of Pakkam tank supply channel.	Gudiyatham	7,300
Under the Control of Superintending Engineer (Food Production)—		
1 Special repairs to Thirumalaikuppam tank ..	Vellore.	46,200
2 Special repairs to Periankuppam tank	Do.	42,200
3 Special repairs to Karai Peria Eri	Wallajah.	6,100
4 Special repairs to Dhoniendukondam tank ..	Do.	10,770
5 Special repairs to Thattacherikondam tank ..	Do.	19,000
6 Special repairs to Velam tank	Do.	9,800
7 Special repairs to Arcot Palar river channel ..	Do.	15,600
8 Special repairs to Veppur Hissathapuram river channel.	Do.	24,900
9 Special repairs to Venkatasamudram Peria Eri ..	Gudiyatham.	20,000
10 Special repairs to Ananthapuram tank	Do.	23,000
11 Special repairs to Perungolathur Peria Eri ..	Cheyyar.	5,800
12 Special repairs to Thenpudipattu tank	Do.	5,300
13 Special repairs to Permbakkam tank	Do.	6,400
14 Special repairs to Sorakkayalnatham tank ..	Tirupattur.	17,100
15 Special repairs to Sevathur tank	Do.	9,900
16 Special repairs to Kadiramangalam tank ..	Do.	2,800
17 Special repairs to Chinnamookanur Eri and supply channel.	Do.	5,600
18 Special repairs to Kuramankuttai tank	Do.	11,100
19 Special repairs to Pachal Hanuman tank ..	Do.	17,600
20 Special repairs to Veerampalli Pudu Eri	Do.	9,500
21 Special repairs to Peddamottur Peria Eri ..	Do.	5,800
22 Special repairs to Mukkanur Melkuttai	Do.	7,300
23 Special repairs to Mutheveri tank	Do.	8,000
24 Special repairs to Appanallur river channel ..	Arni.	12,100
25 Special repairs to Puthur Peria Eri	Do.	11,200
26 Special repairs to Agram Peria Eri	Do.	6,100
27 Special repairs to Adayapalayam Hissa tank ..	Do.	9,000
28 Special repairs to Katteri river channel	Do.	10,700
29 Special repairs to Mullandam Chetteri	Do.	10,800
30 Special repairs to Mullandam Madurikondam ..	Do.	11,300
31 Special repairs to Kalpoondi tank	Do.	2,000
32 Special repairs to Virudukondam	Do.	6,500
33 Special repairs to Viduranthangal	Do.	2,500
34 Special repairs to Vasanthakrishnapuram tank ..	Tiruvannamalai.	73,000
35 Special repairs to Erapakkam tank	Do.	9,000
36 Special repairs to Avoor Peria Eri	Do.	8,500
37 Special repairs to Arapakkam Chitteri	Do.	5,000
38 Special repairs to Devanampattu Eri	Do.	8,300
39 Special repairs to Kuthalamadi Peria Eri ..	Do.	2,300
40 Special repairs to Avar Chitteri	Do	4,700

[28th September 1961

Serial number and name of work.	Taluk.	Estimated cost.
(1)	(2)	(3)
		RS.
Under the Control of Superintending Engineer (Food Production)—cont.		
41 Special repairs to Valiyur Peria Eri	Polur.	16,100
42 Special repairs to Modiyurthangal	Do.	2,900
43 Special repairs to Melpulidiyur tank	Chengam.	11,600
44 Special repairs to Velur Peria Eri	Do.	6,100
45 Special repairs to Perambakkam Chitteri ..	Do.	6,200
46 Special repairs to Morakkanam Eri	Wandiwash.	5,100
47 Special repairs to Kothupakkam tank	Do.	6,200
48 Special repairs to Kilivilliyur tank	Do.	5,200
49 Special repairs to Ammarapuram Kasam channel.	Arkonam.	4,600
50 Special repairs to Ayapadikasam channel ..	Do.	7,600

TAMIL NADU LEGISLATIVE ASSEMBLY
TRUTH ALONE TRIUMPHS
LIBRARY
16 APR 1962
STATE LEGISLATURE, MADRAS